

B.**RECORD CARD FOR SECULAR MONUMENTS.**

(N.B.—Detail of special interest is to be entered here, but described fully on a separate card.)

1. Name and situation of Monument (with owner's Name and Address). *Sneed's Barn
not quite 1½ miles S.S.E. of church (in Olton Valley)*

2. General appearance : (a) No. of storeys. 2 + attics.

(b) Building materials. Stone rubble

(c) Roofs. Stone slates.



County. Herefordshire


Parish. Llanveynoe

Sub-Commission. Seniors

No. of Monument. 11

3. Historical development (with dates and small sketch plan).

*A late 16th or early 17th c. house
at late date turned into barn
& floors removed from E half.
In modern times additions have
been built on against N & E
walls.*



4. Special features (if any).


5. Elevations : (Beginning with the main front, and mentioning, in the following order:—(a) Walls ; (b) Gables ; (c) Doors ; (d) Windows ; (e) Chimneys ; (f) Rainwater heads and pipes.)

S. Elev. Stone rubble. 2 partially blocked ground floor windows.

E. Elev. Gabled on ground floor is a 5-light diamond mullioned window with stop chamfered mullions & there is a similar window at 1st floor level. The base of gable is battered.

N. Elev. There is a 2-light diamond mullioned window frame to staircase with projecting flagstone label & a ground floor a 5-light diamond mullioned blocked window.

W. Elev. Stone wall up to gable level. Gable covered with modern weather board.



6. Grounds : (a)

7. **Interior:** (Disposition of rooms, if original, giving fittings as they occur (see list), beginning with the ground floor, following with the basement, and working up to the attics; staircases in the same manner.)

Fittings :

(Reminder list).

(1) Ceilings.

(2) Cupboards
(fixed).

(3) Doors and
Overdoors.

(4) Fireplaces
and Mantel-
pieces.

(5) Glass.

(6) Paintings.

(7) Panelling.

(8) Parquetry
and floors

(9) Plasterwork
on internal
walls.

(10) Roofs and
beams (in-
ternal).

(11) Screens.


(12) Tapestries.

(13) Miscel-
lanea (e.g.,
carving,
ironwork,
locks, &c.).

On ground floor is a stop chamfered door frame with segmental head to latticed door, with exposed nailheads, hung on pair of strap hinges.

In wall at head of stairs on 1st floor is door frame with segmental head

The rear window lintels are stop chamfered & filled in of thick oak slabs.



8. **Condition :** Bad.

9. **Visited by** (with dates): A.T. Phillips. May. 1927

10. **Bibliography :**

11. **No. of Ordnance Sheet** (6-in.): XLIII. S.E.

12. **Signature of Investigator.**



—47. 500. 12/13. A.&E.W.

P.