

B.


RECORD CARD FOR SECULAR MONUMENTS.

(N.B.—Detail of special interest is to be entered here, but described fully on a separate card.)

1. Name and situation of Monument (with owner's Name and Address). *Firs Farm in Lechom about 2 1/4 miles N.W. of church.*
2. General appearance: (a) No. of storeys. *Porch + building 2 frame, 1 attic. Rest 1 story.*
(b) Building materials. *Stone rubble.*
(c) Roofs. *Stone slate.*

3. Historical development (with dates and small sketch plan).

a 17th c. porch + building probably the same date. It has, however, been much remodelled mostly late in 18th c. In still more recent times additions have been built on at E end + N side.



4. Special features (if any)

5. Elevations: (Beginning with the main front, and mentioning, in the following order:—(a) Walls; (b) Gables; (c) Doors; (d) Windows; (e) Chimneys; (f) Rainwater heads and pipes.)

S. Elev. Porch is gabled + has stop chamfered beam over entrance + above same is a deep projecting stone string. There is a similar string to ground floor window E of porch. Porch has stone seats on either side.

E. Elev. Gabled + exposed timbers. Lower part concealed. Porch has a small slit window.

N. Elev. Nothing quite largely concealed by mod. lean-to.

W. Elev. Gabled. Square stone chimney shaft with projecting string + eap.

Central stack square, stone, with projecting string + 2 course cap.

6. Grounds:



(89,102). Wt. 33,349—47. 5000. 12/13. A. & E. W.
(97,153). „ 5621—53. 8000. 5/14. „

T.O.

County.

Herefordshire I

Parish.

Llanveyneoe

Sub-Commission.

Sealer.

No. of Monument.


11

7. **Interior:** (Disposition of rooms, if original, giving fittings as they occur (see list), beginning with the ground floor, following with the basement, and working up to the attics: staircases in the same manner.)

Fittings:

(Reminder list).

- (1) Ceilings
- (2) Cupboards (fixed).
- (3) Doors and Overdoors.
- (4) Fireplaces and Mantel-pieces.
- (5) Glass.
- (6) Paintings.
- (7) Panelling.
- (8) Parquetry and floors.
- (9) Plasterwork on internal walls.
- (10) Roofs and beams (internal).
- (11) Screens.
- (12) Tapestries.
- (13) Miscellaneous (e.g., carving, ironwork, locks, &c.).



Ceilings of all ground floor rooms have chamfered beams (those in room w. porch are papered over) & some exposed joists.
Ceiling of porch has exposed chamfered joists with moulded stops.

8. **Condition:** Poor.

9. **Visited by** (with dates): A.T. Phillips. 1927.

10. **Bibliography:**

11. **No. of Ordnance Sheet** (6-in.): XLIII. N.E.

12. **Signature of Investigator.** A.T. Phillips.



47. 500. 12/13. A.&E.W.