

B.

RECORD CARD FOR SECULAR MONUMENTS.


(N.B.—Detail of special interest is to be entered here, but described fully on a separate card.)

1. Name and situation of Monument (with owner's Name and Address). *Blaen-Olchon*
at head of Olchon Valley & about 2 1/2 miles N.W. of Church
2. General appearance: (a) No. of storeys. *1 + attic*
(b) Building materials. *Stone rubble*
(c) Roofs. *W half gable stone slates. Remainder modern slates.*



3. Historical development (with dates and small sketch plan).

The western portion of house is c 1700 while the W half is probably slightly earlier. In modern times it has been somewhat re-modelled.



4. Special features (if any)

5. Elevations: (Beginning with the main front, and mentioning, in the following order:—(a) Walls; (b) Gables; (c) Doors; (d) Windows; (e) Chimneys; (f) Rainwater heads and pipes.)


S. Elev. Stone rubble. 1/3 light casement with wood frame mullions plain on exterior & moulded on interior side (frame repaired externally).

W. Elev. Gabled. Rectangular outside stack, weathered on N side, square shaft with projecting string. There is a blocked window to attic.

E. Elev. Gabled. Gable partly re-built.

N. Elev. Projection has lean-to roof. Immediately E of same is modern lean-to. On ground floor is a small one light square window with wide internal splay.

6. Grounds: (a)



County.

Herefordshire

Parish.

Llanveyne

Sub-Commission.

Secular

No. of Monument.


27

7. Interior: (Disposition of rooms, if original, giving fittings as they occur (see list), beginning with the ground floor, following with the basement, and working up to the attics; staircases in the same manner.)

Fittings:

(Reminder list).

- (1) Ceilings
- (2) Cupboards (fixed).
- (3) Doors and Overdoors.
- (4) Fireplaces and Mantel-pieces.
- (5) Glass.
- (6) Paintings.
- (7) Panelling.
- (8) Parquetry and floors.
- (9) Plasterwork on internal walls.
- (10) Roofs and beams (internal).
- (11) Screens.
- (12) Tapestries.
- (13) Miscellaneous (e.g., carving, ironwork, locks, &c.).



Ground floor ceilings have exposed ^{stop} chamfered beams & joists.

8. Condition: *Fair*.

9. Visited by (with dates):

A.T. Phillips. May. 1927.

10. Bibliography:

11. No. of Ordnance Sheet (6-in.): *XLIII. N.E.*

12. Signature of Investigator.

A.T. Phillips

