

B.


RECORD CARD FOR SECULAR MONUMENTS.

(N.B.—Detail of special interest is to be entered here, but described fully on a separate card.)

1. Name and situation of Monument (with owner's Name and Address). *Wern Farm (described used as barn) 1/4 mile S of Church.*
2. General appearance: (a) No. of storeys. *1 + attic.*
(b) Building materials. *Stone rubble.*
(c) Roofs. *Stone on S.E. Cor. Iron on N.W.*

3. Historical development (with dates and small sketch plan).

*a late 16th or early 17th c. house.
In modern times a barn has been built on at S.W. end.*



4. Special features (if any).

5. Elevations: (Beginning with the main front, and mentioning, in the following order:—(a) Walls; (b) Gables; (c) Doors; (d) Windows; (e) Chimneys; (f) Rainwater heads and pipes.)


N.W. Elev. Two ground floor windows have old wood frames + flag stone projecting labels.

N.E. Elev. Gabled. Exposed timbers. There is a projecting outside stack to 1st floor with rectangular base supported on stone corbels and square stone shaft with projecting cap. There is a window at 1st floor level with old wood frame.

S.E. Elev. On ground floor is a blocked window or window with old wood frame. There is a lean-to roof projecting bay containing a semicircular stone staircase.

S.W. Elev. Gabled but mostly hidden by barn.

6. Grounds:



(89,102). Wt.33,149—47. 500. 12/13. A.&E.W.
(97,153). „ 5621—53. 6000. 5/14. „

P.T.O.

County. *Herefordshire*

Parish. *Llanveyneoe*

Sub-Commission. *Secular*


No. of Monument. *8*

7. Interior: (Disposition of rooms, if original, giving fittings as they occur (see list), beginning with the ground floor, following with the basement, and working up to the attics; staircases in the same manner.)

Fittings:

(Reminder list).

- (1) Ceilings.
- (2) Cupboards (fixed).
- (3) Doors and Overdoors.
- (4) Fireplaces and Mantel-pieces.
- (5) Glass.
- (6) Paintings.
- (7) Panelling.
- (8) Parquetry and floors
- (9) Plasterwork on internal walls.
- (10) Roofs and beams (internal).
- (11) Screens.
- (12) Tapestries.
- (13) Miscellaneous (e.g., carving, ironwork, locks, &c.).



Ground floor ceiling has a stop chamfered cross beam & exposed stop chamfered joists of heavy scantling.
Beneath the cross beam is a framed partition with wood panels.

8. Condition: *Bad.*

9. Visited by (with dates): *A.T. Phillips. May. 1927.*

10. Bibliography:

11. No. of Ordnance Sheet (6-in.): *XLIII. N.E.*

12. Signature of Investigator. *A.T. Phillips*

Gabled but mostly hidden by barn.



45 500 12/12 A & E IV

P